

## Inspection Photos

Location Name: WILHITE-67N64W/30SESW

Location #: 306508



**Photo #1**

**Wilhite 30-34 (123-24807) Wellsite**

**Temporarily Abandoned | TA**

***Vegetation overgrowth***



**Photo #2**

**Wilhite 30-34, Wagner 30-32 Battery site**

**Inactive | Shut-down**

***Equipment documented: Loc. ID 306508***

***Formerly served:***

***Wilhite 30-31, Wagner 30-33, 30-35;***

***Plugged & Abandoned | PA***



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: WILHITE-67N64W/30SESW

Location #: 306508



### Photo #3

Wilhite 30-34, Wagner 30-32 Battery site

**Inactive | Shut-down**

*Battery entrance*

*Well(s) entrance: Wilhite 30-34*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources