

Inspection Photos

Location Name: WILHITE-67N64W/30SESW

Location #: 306508



Photo #1

Wilhite 30-34, Wagner 30-32 Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 306508

Formerly served:

Wilhite 30-31, Wagner 30-33, 30-35;

Plugged & Abandoned | PA



Photo #2

Wilhite 30-34, Wagner 30-32 Battery site

Inactive | Shut-down

Battery entrance

Well(s) entrance: Wilhite 30-34



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: WILHITE-67N64W/30SESW

Location #: 306508



Photo #3

Wilhite 30-34, Wagner 30-32 Battery site

Inactive | Shut-down

Crude Oil tank(s), Produced H2O vault(s); SE corner



Photo #4

Wilhite 30-34, Wagner 30-32 Battery site

Inactive | Shut-down

Separator(s), ECD(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WILHITE-67N64W/30SESW
Location #: 306508



Photo #5
Wilhite 30-34, Wagner 30-32 Battery site
Inactive | Shut-down
Battery signage 1



Photo #6
Wilhite 30-34, Wagner 30-32 Battery site
Inactive | Shut-down
Battery signage 2



Inspection Photos

Location Name: WILHITE-67N64W/30SESW

Location #: 306508

Associated Well(s)	API	Location	Status
1. Wilhite 30-34	123-24807	306508	TA
2. Wagner 30-32	123-26227	310319	TA

Photo #7

Wilhite 30-34, Wagner 30-32 Battery site

Inactive | Shut-down

Associated well(s)

2: Temporarily Abandoned | TA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources