

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2025

Submitted Date:

07/23/2025

Document Number:

707604096

FIELD INSPECTION FORM

Loc ID 310319 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 292056 | WELL | TA | 12/20/2024 | GW | 123-26227 | WAGNER 30-32 | TA |

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (306508, 310319).
(Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery formerly served 3 Location IDs (306507, 306509, 306562).
(Well(s): 3: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707604094 and/or Location ID #306508 for TA Well(s) info.
B.) Field Inspection Report doc. #707604096 and/or Location ID #310319 for TA Well(s) info.
C.) Field Inspection Report doc. #707604098 and/or Location ID #306508 for Battery / Facility, Equipment info.

| Location | | | |
|--|--|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | *Refer to Emergency Contact Number section below. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Wellsite: OOSLAT applied. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | CORRECTIVE GUIDANCE COMMENT(s): 1. Invalid Emergency contact number posted at wellsite. Refer to Rule 605.d for guidance. Post valid Emergency contact number at wellsite. Comply with Rule 605.d. See photo(s) #1. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: | Horizontal Heated Separator | # 0 | corrective date |
| Comment: | Equipment assigned to Loc ID #306508. | | |
| Corrective Action: | | Date: | |
| Type: | Gas Meter Run | # 0 | |
| Comment: | Equipment assigned to Loc ID #306508. | | |
| Corrective Action: | | Date: | |
| Type: | Emission Control Device | # 0 | |
| Comment: | Equipment assigned to Loc ID #306508. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------|
| Type: Pig Station | # 0 | | |
| Comment: | Equipment assigned to Loc ID #306508. | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 0 | | |
| Comment: | Temporarily Abandoned TA. Equipment removed. | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 0 | | |
| Comment: | Equipment assigned to Loc ID #306508. | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------------|----------|------|---------|--------|
| PRODUCED WATER | 0 | | | | |
| Comment: | Equipment assigned to Loc ID #306508. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------------|----------|------|---------|--------|
| CRUDE OIL | 0 | | | | |
| Comment: | Equipment assigned to Loc ID #306508. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 292056 Type: WELL API Number: 123-26227 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
ECMC records last production: 03/2021.

Form 4 on file. TA date: 12/10/2024. Approval Pending.
DH-RBP set. Date: 12/10/2024. Approved.
Form 21 MIT, Date: 02/20/2023. Approved.
Form 5B Inactive Well notice on file.
Defined Inactive Date: 10/16/2024.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>CECMC Inspection Report Synopsis:</p> <p>On WED 07/16/2025 at approximately 15:53 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: WAGNER-67N64W/30NWSW Location ID: 310319 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1:Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>**CORRECTIVE GUIDANCE COMMENT(s): 1. Refer to pg 2, Good Housekeeping section.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p> | evinsb | 07/23/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 707604097 | Inspection photo(s) | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7156051 |