

## Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 7/17/2025



Location Overview – Photo #09819



Location – Photo #09820

## Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 7/17/2025



Location – Photo #09825



Location – Photo #09822

## Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 7/17/2025



Location – Photo #09826



PRV Terminates in Unsafe Manner – Photo #09823

## Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 7/17/2025



**PRV Terminates in Unsafe Manner – Photo #09824**