

Inspection Photos

July 16th, 2025

Operator: Redwine Resources Inc.

Location ID: 393396

Inspection Document #: 714002313

Montrose County, CO

Township: SENW 5 46N 14W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: South Nucla Unit 5-22

Location ID: 393396

July 16, 2025
338° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of project area taken from the southern edge facing center.

API #: 085-06046

Inspection Photos

Location Name: South Nucla Unit 5-22

Location ID: 393396



Inspection Photos

Location Name: South Nucla Unit 5-22

Location ID: 393396



Photo 3. Cardinal photos taken from the center of the project area. Left Photo facing south, right photo facing west. Note: area appears to have been mowed (large chunks of crushed wood) and grazed vegetation.

Inspection Photos

Location Name: South Nucla Unit 5-22

Location ID: 393396

July 16, 2025
238° SW



Photo 4. Reference area composed of Juniper, sagebrush and Indian Ricegrass.

