



Musick-McClintock 5 (Spill ID 481685/REM 23556)
Approximately 60'x50'x12' (LxWxD) remedial excavation remains open
-Cattle fencing has been installed around the open excavation
-Weeds/vegetation throughout the area disturbed by site investigation and remediation activities and throughout the open excavation




Musick-McClintock 5 (Spill ID 481685/REM 23556)

Approximately 60'x50'x12' (LxWxD) remedial excavation remains open

-Cattle fencing has been installed around the open excavation


-Weeds/vegetation throughout the area disturbed by site investigation and remediation activities and throughout the open excavation

-Flowline exposed within the open excavation



Musick-McClintock 5 (Spill ID 481685/REM 23556)

- Approximately 60'x50'x12' (LxWxD) remedial excavation remains open
- Cattle fencing has been installed around the open excavation
- Weeds/vegetation throughout the area disturbed by site investigation and remediation activities and throughout the open excavation
- Spill is located adjacent to Weld County Road 40
- Property fencing to the north and NE of the excavation has been removed and remains open



Musick-McClintock 5 (Spill ID 481685/REM 23556)

- Approximately 60'x50'x12' (LxWxD) remedial excavation remains open
- Cattle fencing has been installed around the open excavation
- Weeds/vegetation throughout the area disturbed by site investigation and remediation activities and throughout the open excavation
- Spill is located adjacent to Weld County Road 40
- Property fencing to the north and NE of the excavation has been removed and remains open



Musick-McClintock 5 (Spill ID 481685/REM 23556)

-Wattles around the E&P waste stockpile (approximately 70'x35') need to be replaced.

“Contaminated” signage previously observed (See FIR Doc #689501335 & 702700147) at the stockpile has been removed; however, the E&P waste stockpile remains and is now overgrown with weeds.