

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 7/22/2025



Location Overview – Photo #09851



Location – Photo #09852

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 7/22/2025



Location – Photo #09853

Illegible Battery Sign – Photo #09854

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 7/22/2025



Unserviceable Containment Liner – Photo #09855




Unserviceable Containment Liner – Photo #09856

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 7/22/2025



Unserviceable Containment Liner – Photo #09857



Unserviceable Containment Liner – Photo #09858

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 7/22/2025



Unserviceable Containment Liner – Photo #09859



Unserviceable Containment Liner – Photo #09860