

WELL SITE INSPECTION FOR



Well Name Danford Champlin 4-4 API Number 05 - 001 - 8124

Operator Benson Minerals Permit # _____

Location SWNW 4-35-64w County Adams

Field Bear Gulch Inspector Binkley

AL/PA/DA Inspection Results: Well Status:

Pass (Y) Fail (N) _____ Date 7-23-90 FN _____ FD _____ WO _____ PR _____ SI _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____

Consistent with APD casing Program? YES _____ NO _____ Returns _____

Rig _____ BOP'S _____ Contact _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____

Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____

Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLS

Equipment _____ Meter Run: Yes _____ No _____

Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____

Hole Plugged: Yes No _____ Pits Backfilled: Yes No _____

Material Buried: Yes No _____ N/A _____ Site Clean: Yes No _____

Bond Release OK: Yes No _____ Fed _____ Hole Marker: Yes _____ No

Date of Safety/Status Inspection _____

Comments: Plugged

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____