

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)



(C)

Well Name 4-4 Danford API Number 05-001-9124
Operator Benson Min Permit # _____
Location SWNW 4-3564 County Adams
Field Bear Gulch Inspector Bail Day

AL/PA/DA Inspection Results: Well Status:
Pass(Y) Fail(N) _____ Date 10-11-91 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

=====
Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes No _____ Pits Backfilled: Yes No _____
Material Buried: Yes No _____ N/A _____ Site Clean: Yes No _____
Bond Release OK: Yes No _____ Fed _____ Hole Marker: Yes _____ No

Date of Safety/Status Inspection _____

Comments: Site originally plowed by Benson Min.
Rain has washed out north edge of wellsite
this is in drainage contour. Remaining wellsite
although weed covered is in contour w/ farmland
Some gravel is present and blended in soil.

ACCEPT AS PA=7, SDK

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____