

Inspection Photos

06/16/2025

Operator: BONANZA CREEK ENERGY OPERATING
LLC- #8960

Location ID: 324618

Inspection Document #: 712300168

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mccallum Unit # 64 Pad
Location ID: 324618



Photo 1. Photo taken from the center of the previous disturbance, facing north, east, south, and west. Vegetation has reached 80% of the reference area and is primarily sagebrush and *Hilaria jamesii*.



Photo 2. See comments under Photo 1.

Inspection Photos
Location Name: Mccallum Unit # 64 Pad
Location ID: 324618



Photo 3. See comments under Photo 1.



Photo 4. See comments under Photo 1.



Inspection Photos
Location Name: Mccallum Unit # 64 Pad
Location ID: 324618



Photo 5. Photo taken from the entrance to the Location, facing south. Fence remains around the pad.



Photo 6. Photos 6-8 taken of the access road, illustrating that the access road is experiencing erosion, primarily in the portion closest to the pad entrance.

Inspection Photos
Location Name: Mccallum Unit # 64 Pad
Location ID: 324618



Photo 7. See comments under Photo 6.



Photo 8. See comments under Photo 6.



Inspection Photos
Location Name: Mccallum Unit # 64 Pad
Location ID: 324618



Photo 9. Photos 9-10 taken of the reference area vegetation, illustrating primarily sagebrush vegetation.



Photo 10. See comments under Photo 9.