


Inspection Photos
Location Name: Bennett State 8-16-5-45 (OWP)
API Number: 125-09854



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Bennett State 8-16-5-45 (OWP)
API Number: 125-09854



3. View of wellhead.



4. View of wellhead. Water was poured on tubing head as visual aid to create bubbles. No fluid coming from well.

Inspection Photos
Location Name: Bennett State 8-16-5-45 (OWP)
API Number: 125-09854



5. Lease sign at shared gathering location.



6. Vertical separator inside shed.

Inspection Photos
Location Name: Bennett State 8-16-5-45 (OWP)
API Number: 125-09854



7. Gas meter inside shed.



8. View of Shed off cribbing causing it to lean.

Inspection Photos
Location Name: Bennett State 8-16-5-45 (OWP)
API Number: 125-09854



9. View of one of the flowlines bent over due to shed movement off cribbing.



10. Shared gathering location overview.