

Final Reclamation Inspection

June 25, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 418266

Inspection Document #: 718800531

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON H #35-22X
Location ID: 418266



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: CANNON H #35-22X
Location ID: 418266



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CANNON H #35-22X
Location ID: 418266



Photo 5. Photo taken of ground cover at the location. Photo illustrates weedy annual vegetation, including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the well location, facing northwest. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards and the site is dominated by russian thistle (*Salsola tragus*).

Inspection Photos
Location Name: CANNON H #35-22X
Location ID: 418266



Photo 7. Photo taken of the reference area to the well location, south of the location, facing west. Photo illustrates the site is dominated by sand sagebrush (*Artemisia filifolia*) and prairie sunflower (*Helianthus petiolaris*).

