

Final Reclamation Inspection

June 25, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328319

Inspection Document #: 718800533

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON #H 35-10
Location ID: 328319



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: CANNON #H 35-10
Location ID: 328319



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: CANNON #H 35-10
Location ID: 328319



Photo 5. Photo taken of ground cover at the location. Photo illustrates weedy annual vegetation, including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the well location, facing south. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: CANNON #H 35-10
Location ID: 328319



Photo 7. Photo taken of the reference area to the well location, south of the location, facing east. Photo illustrates the site is dominated by sand sagebrush (*Artemisia filifolia*) and prairie sunflower (*Helianthus petiolaris*).

