

# Construction and Stormwater Inspection

June 27, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 489258

Inspection Document #: 718800550

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: T-Bone/XOG-28 Pad  
Location ID: 489258



**Photo 1.** Photo taken from the entrance to the location. Photo illustrates the Operator sign. No mailbox or permits were observed at the time of this inspection.



**Photo 2.** Photo taken of the entrance to the location, facing northeast. Photo illustrates that ditch and berm BMPs have not been installed along the perimeter of the location.

Inspection Photos  
Location Name: T-Bone/XOG-28 Pad  
Location ID: 489258



**Photo 3.** Photo taken from the southern perimeter of the location, facing north. Photo illustrates culverts have been installed near the southwestern entrance to the location.



**Photo 4.** Photo taken from the southern perimeter of the location, facing northwest. Photo illustrates the operator is in the process of stabilizing the working pad surface.



Inspection Photos  
Location Name: T-Bone/XOG-28 Pad  
Location ID: 489258



**Photo 5.** Photo taken of the southern perimeter of the location, facing north. See comments under Photo 4.



**Photo 6.** Photo taken of the eastern entrance to the location along the southern perimeter. Photo illustrates a culvert has been installed and the operator was in the process of stabilizing the entrance with road base.

Inspection Photos  
Location Name: T-Bone/XOG-28 Pad  
Location ID: 489258



**Photo 7.** Photo taken of the eastern entrance to the location along the southern perimeter. Photo illustrates that at the time of this inspection rock was being installed to create a vehicle tracking pad.



**Photo 8.** Photo taken from southeastern perimeter of the location, facing northeast. Photo illustrates a porta potty has been stabilized per best management practices. The operator is in the process of installing a ditch and berm along this portion of the location.

Inspection Photos  
Location Name: T-Bone/XOG-28 Pad  
Location ID: 489258



**Photo 9.** Photo taken from the eastern portion of the location. Photo illustrates the operator is in the process of stabilizing the working pad surface.



**Photo 10.** Photo taken from the northeastern portion of the location, facing southwest. See comments under Photo 9.

Inspection Photos  
Location Name: T-Bone/XOG-28 Pad  
Location ID: 489258



**Photo 11.** Photo taken from the northern perimeter of the site, facing southeast. See comments under Photo 9.



**Photo 12.** Photo taken of the topsoil stockpile. Photo illustrates the operator has not yet stabilized the stockpile.



Inspection Photos  
Location Name: T-Bone/XOG-28 Pad  
Location ID: 489258



**Photo 13.** Photo taken of the southwestern portion of the location, facing south. See comments under Photo 9.



**Photo 14.** Photo taken of the southwestern portion of the location, facing north. See comments under Photo 9.