

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 3966 From entrance to location



Photo # 3967 From entrance to location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-14 Pad  
Location # 335853




Photo # 3968 Location

Photo # 3969 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 3970 Location



Photo # 3971 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 3972 Location



Photo # 3973 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 3974 Location



Photo # 3975 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-14 Pad

Location # 335853



Jul 23, 2025 at 4:36:56 PM  
CO

**Photo # 3976 – 2 condensate tanks & 1 produced water tank  
In battery on location. FORM 2A document # 400099288 lists  
no condensate or produced water tanks/not in compliance  
with CECMC rules. Additionally liquid nitrogen tank &  
chemical tank on location are not list in FORM 2A or FORM 4  
SUNDRY/not in compliance with CECMC rules.**