

Final Reclamation Inspection

July 8, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 447067

Inspection Document #: 718800559

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CORBIN RED D 30-4J,9,15,16

Location ID: 447067



Photo 1. Photo taken of the western portion of the tank battery location, facing southwest. Photo illustrates that the location does not meet Rule 1004 standards as gravel and weedy annual vegetation were observed across the location.



Photo 2. Photo taken of the western portion of the tank battery location, facing southeast. See comments under Photo 1.



Inspection Photos

Location Name: CORBIN RED D 30-4J,9,15,16

Location ID: 447067



Photo 3. Photo taken from the western portion of the tank battery location, facing west. Photo illustrates that gravel remains on the location.



Photo 4. Photo taken of the western portion of the tank battery location, facing east. See comments under Photo 3.



Inspection Photos

Location Name: CORBIN RED D 30-4J,9,15,16

Location ID: 447067



Photo 5. Photo taken of ground cover at the tank battery location. Photo illustrates gravel and weedy annual vegetation.



Photo 6. Photo taken from the eastern portion of the tank battery location, facing southeast. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but gravel and weedy annual vegetation were observed across the location.



Inspection Photos

Location Name: CORBIN RED D 30-4J,9,15,16

Location ID: 447067



Photo 7. Photo taken of the eastern portion of the tank battery location, facing east. See comments under Photo 6.



Photo 8. Photo taken from the eastern portion of the tank battery location, facing west. See comments under Photo 6.



Inspection Photos

Location Name: CORBIN RED D 30-4J,9,15,16

Location ID: 447067



Photo 9. Photo taken of the access road to the tank battery location, facing southeast. Photo illustrates that final reclamation has not taken place along the access road and it appears to remain in use by the landowner.



Photo 10. Photo taken of ground cover at the tank battery. Photo illustrates gravel and weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, and kochia (*Bassia scoparia*).



Inspection Photos

Location Name: CORBIN RED D 30-4J,9,15,16

Location ID: 447067



Photo 11. Photo taken of the reference area to the tank battery location, north of the location, facing northwest. Photo illustrates perennial grass and annual vegetation.

