

Final Reclamation Inspection

July 8, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329059

Inspection Document #: 718800562

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CORBIN RED D #30-9
Location ID: 329059



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards as the site is dominated by weedy annual vegetation and fencing remains in disrepair around the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: CORBIN RED D #30-9
Location ID: 329059



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CORBIN RED D #30-9
Location ID: 329059



Photo 5. Photo taken of ground cover at the location. Photo illustrates that fencing remains around the location and is in disrepair. Weedy annual vegetation, including kochia (*Bassia scoparia*), was observed across the location.



Photo 6. Photo taken of the access road to the well location, facing east. Photo illustrates that weedy annual vegetation remains along the access road.

Inspection Photos
Location Name: CORBIN RED D #30-9
Location ID: 329059



Photo 7. Photo taken of the reference area to the well location, southeast of the location, facing east. Photo illustrates the site is dominated by annual vegetation including Rocky Mountain beeplant (*Cleomella serrulate*) and cheatgrass (*Bromus tectorum*).

