

Final Reclamation Inspection

July 8, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 309822

Inspection Document #: 718800564

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCWILLIAMS D #29-32
Location ID: 309822



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards as the site is dominated by weedy annual vegetation and fencing remains around the location in disrepair.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: MCWILLIAMS D #29-32
Location ID: 309822



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: MCWILLIAMS D #29-32

Location ID: 309822



Photo 5. Photo taken of ground cover at the location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of fencing along the western perimeter of the well location, facing North. Photo illustrates that fencing remains at the location. Bare ground and weedy annual vegetation was observed across the location.



Inspection Photos
Location Name: MCWILLIAMS D #29-32
Location ID: 309822



Photo 7. Photo taken of fencing along the access road to the location, facing northeast. Photo illustrates that fencing remains and is in disrepair.



Photo 8. Photo taken of the access road to the well location, facing north. Photo illustrates that bare ground and weedy annual vegetation remain along the access road.



Inspection Photos
Location Name: MCWILLIAMS D #29-32
Location ID: 309822



Photo 9. Photo taken of the reference area to the well location, southeast of the location, facing north. Photo illustrates the reference site is dominated by annual vegetation including Rocky Mountain beeplant (*Cleomella serrulate*) and cheatgrass (*Bromus tectorum*).

