

Final Reclamation Inspection

July 8, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 458825

Inspection Document #: 718800573

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Moser
Location ID: 458825



Photo 1. Photo taken of the tank battery location, facing west. Photo illustrates that the final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards as the location is dominated by weedy annual vegetation.



Photo 2. Photo taken of the tank battery location, facing northwest. See comments under Photo 1. Gravel and bare ground remain across the access road adjacent to the location (see Photo 4).



Inspection Photos
Location Name: Moser
Location ID: 458825



Photo 3. Photo taken of the tank battery location, facing north. See comments under Photo 1.



Photo 4. Photo taken of the access road to the tank battery location, facing west. Photo illustrates that final reclamation activities do not appear to have taken place along the access road as gravel and bare ground remain.



Inspection Photos
Location Name: Moser
Location ID: 458825



Photo 5. Photo taken of ground cover at the tank battery location. Photo illustrates cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of ground cover along the access road for the tank battery. Photo illustrates gravel and weedy annual vegetation.

Inspection Photos
Location Name: Moser
Location ID: 458825



Photo 7. Photo taken of the reference area to the tank battery location, east of the location, facing east. Photo illustrates perennial grass and annual grass vegetation.