

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0392 Entrance to location



Photo # 0400 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0393 Location



Photo # 0406 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0456 NE corner of location



Photo # 0457 SE corner of location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0458 SW corner of location



Photo # 0459 NW corner of location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0401 Unused equipment - Chemical tank is not in use/unused equipment



Photo # 0402 Unused equipment - Chemical tank is not in use/unused equipment

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



**Photo # 0405 Chemical tank port is open to wildlife/available for entry by wildlife**



**Photo # 0410 PRV vent lines do not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0419 Battery sign is in disrepair and lacks quarter/quarter section information/not in compliance with CECMC rules



Photo # 0426 Open ended piping/wildlife hazard/available for entry by wildlife

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



**Photo # 0428 Hole in tank/wildlife hazard/available for entry by wildlife**



**Photo # 0432 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



**Photo # 0435 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard**



**Photo # 0422 Tank showing signs of rust. All in-service Tanks and process vessels will be inspected and maintained**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0449 Debris on location



Photo # 0451 Debris on location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 22 PAD

Location ID: 315359

Date: 07/21/2025



Photo # 0454 Debris on location



Photo # 0455 Debris on location