

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 4111 From entrance to location

Photo # 4112 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 4113 Location



Photo # 4114 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 4115 Location



Photo # 4116 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 4117 Location



Photo # 4118 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 4119 Location



Photo # 4120 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 4121 Staining



Photo # 4122 Debris