

# Inspection Photos

06/13/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 383325

Inspection Doc: 719200035

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383325



**Photo 1:** Photo taken from the east-central portion of the location and provides an overview looking south and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383325

Jun 13, 2025 at 11:58:31 AM  
6338 Divide Creek Rd  
Silt CO 81647  
United States



Jun 13, 2025 at 11:58:47 AM  
6338 Divide Creek Rd  
Silt CO 81647  
United States



**Photo 2:** Photo taken from the central portion of the location and provides an overview looking north and east, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383325



**Photo 3:** Photo taken at the northwestern perimeter of the pad showing light erosion and sediment transport off the location. Maintenance is advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383325



**Photo 4:** Photos taken from the eastern and northern portions of the interim area, respectively. The interim areas do not appear to be progressing towards 1003 requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383325



**Photo 5:** Photos taken from the southeastern portion of the interim area at the location looking north. The interim areas do not appear to be progressing towards 1003 requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383325



**Photo 6:** Photo taken provides an overview of the western interim location. The interim areas do not appear to be progressing towards 1003 requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383325



**Photo 7:** Photo shows light sediment tracking on the pad. Erosion and sediment tracking control BMP's are recommended. Maintenance is advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources