

Inspection Photos

06/13/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 423439

Inspection Doc: 719200036

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 423439

Jun 13, 2025 at 12:21:26 PM



Jun 13, 2025 at 12:21:45 PM



Photo 1: Photo taken from the southern portion of the pad and provide an overview looking northwest and northeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 423439



Photo 2: Photos taken from the southern portion of the pad and provide an overview looking southeast and east, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 423439



Photo 3: Photos taken from the northern portion of the pad. Stormwater outlets appear to be in disrepair. Maintenance is advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 423439



Photo 4: Photo taken shows a chemical tank that appears to be disconnected. Maintenance or removal is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 423439



Photo 5: Photos taken from the southern portion of the pad and provide an overview looking at the southern interim area. Native grasses such as western wheatgrass and intermediate wheatgrass have established; this portion of the interim area appears to be progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 423439



Photo 6: Photos taken from the southern portion of the pad and provide an overview looking at the southern interim area. Reclamation in this area is not progressing towards 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 423439



Photo 7: Photos taken from the southern portion of the pad and provide an overview looking at the northern interim area. This portion of the interim location is not progressing towards 1003 reclamation standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources