

Inspection Photos
Location Name: Fox Creek 505-2501H PAD
Location ID: 416477



Photo 1 – Locate Flags – Trash



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Fox Creek 505-2501H PAD
Location ID: 416477




Photo 3 – Stained Soil at 504-2524H Wellhead

Photo 4 – Unmarked Riser at 504-2524H Wellhead

Inspection Photos
Location Name: Fox Creek 505-2501H PAD
Location ID: 416477



Photo 5 – Wellhead Sign

Photo 6 – Trash

Inspection Photos
Location Name: Fox Creek 505-2501H PAD
Location ID: 416477



Photo 7 – Trash



Photo 8 – Unused Riser – 25-2501H

Inspection Photos
Location Name: Fox Creek 505-2501H PAD
Location ID: 416477



Photo 9 – Pumping Unit