

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 1 – Separators



Photo 2 – Gas Meters

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 3 – Tank Battery



Photo 4 – Stained Soil at South Loadline Buckets

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563




Photo 5 – Tank Battery Signs/Labels

Photo 6 – Tank Battery Signs

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 7 – Stained Soil at North Tank

Photo 8 – Stained Soil at North Tank

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 9 – Stained Soil at North Tank

Photo 10 – Stained Soil at North Tank

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 11 – Stained Soil at North Tank

Photo 12 – Stained Soil at North Tank

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 13 – Stained Soil at North Tank

Photo 14 – Unused Installation Tubes

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 15 – ECDs



Photo 16 – Separator

Inspection Photos
Location Name: Fox Creek 505-2501H Tank Battery
Location ID: 481563



Photo 17 – Gas Meters