

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC NOLTE 14-43D Pad

Location #: 324087



Photo # 5160 From entrance to location



Photo # 5161 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC NOLTE 14-43D Pad

Location #: 324087



Photo # 5162 Location




Photo # 5163 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC NOLTE 14-43D Pad

Location #: 324087



Jul 28, 2025 at 12:28:32 PM  
CO



Jul 28, 2025 at 12:28:49 PM  
CO

Photo # 5164 Location

Photo # 5165 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC NOLTE 14-43D Pad

Location #: 324087



Photo # 5166 Location



Photo # 5167 Sign on dehy has previous operator

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC NOLTE 14-43D Pad

Location #: 324087



**Photo # 5168 Open ended piping on dehy/wildlife hazard/available for entry by wildlife**



**Photo # 5169 Open ended piping on dehy/wildlife hazard/available for entry by wildlife**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC NOLTE 14-43D Pad

Location #: 324087



**Photo # 5170 Open ended piping on dehy/wildlife hazard/available for entry by wildlife**



**Photo # 5171 Open ended piping on dehy/wildlife hazard/available for entry by wildlife**