

Final Reclamation Inspection

July 10, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328204

Inspection Document #: 718800582

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNCAN D #20-1
Location ID: 328204



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards. Bare ground and weedy annual vegetation were observed across the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-1
Location ID: 328204



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-1
Location ID: 328204



Photo 5. Photo taken of the access road to the well location, facing northeast. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards and the access road is dominated by weedy annual vegetation including cheatgrass (*Bromus tectorum*).



Photo 6. Photo taken of the access road to the well location, facing northeast. Photo illustrates stormwater erosion along portions of the access road.

Inspection Photos
Location Name: DUNCAN D #20-1
Location ID: 328204



Photo 7. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation was observed across the location, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 8. Photo taken of the tank battery location, facing southwest. See comments under Photo 7.

Inspection Photos
Location Name: DUNCAN D #20-1
Location ID: 328204



Photo 9. Photo taken of the reference area to the well location, south of the location, facing northeast. Photo illustrates sand sagebrush (*Artemisia filifolia*) and cheatgrass (*Bromus tectorum*).