

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328219

Inspection Document #: 718800584

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNCAN D #20-7
Location ID: 328219



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards. The site has been recently mowed.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-7
Location ID: 328219



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-7
Location ID: 328219



Photo 5. Photo taken of ground cover at the well location. Photo illustrates that the site was recently mowed.



Photo 6. Photo taken of the access road to the well location, facing south. Photo illustrates that bare ground remains across the access road.



Inspection Photos
Location Name: DUNCAN D #20-7
Location ID: 328219



Photo 7. Photo taken of the tank battery location, facing south. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation was observed across the location, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*).



Photo 8. Photo taken of the tank battery location, facing west. See comments under Photo 7.



Inspection Photos
Location Name: DUNCAN D #20-7
Location ID: 328219



Photo 9. Photo taken of the tank battery location, facing east. See comments under Photo 7.



Photo 10. Photo taken of ground cover at the tank battery location. Photo illustrates weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Inspection Photos
Location Name: DUNCAN D #20-7
Location ID: 328219



Photo 11. Photo taken of the midstream equipment that remains at the tank battery location. Photo illustrates that equipment is in disrepair.



Photo 12. Photo taken of the reference area, southeast of the location, facing southeast. Photo illustrates perennial grass vegetation.