

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 332003

Inspection Document #: 718800595

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GUTTERSEN #10-20
Location ID: 332003



Photo 1. Photo taken from the well location, facing North. Photo illustrates that the well location appears to meet Rule 1004 standards. However, the location has been recently mowed and vegetation establishment will be inspected at a later date.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: GUTTERSEN #10-20
Location ID: 332003



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: GUTTERSEN #10-20
Location ID: 332003



Photo 5. Photo taken of the access road to the location, facing southeast, away from the location. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. The site has been recently mowed and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed across the access road.



Photo 6. Photo taken of the access road to the well location, facing northwest, towards the well location. See comments under Photo 5.



Inspection Photos
Location Name: GUTTERSEN #10-20
Location ID: 332003



Photo 7. Photo taken of the reference area south of the location, facing south. Photo illustrates perennial grass vegetation and sand sagebrush (*Artemisia filifolia*).