

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328052

Inspection Document #: 718800597

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNCAN D #20-10
Location ID: 328052



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards as the site is dominated by weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*).



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: DUNCAN D #20-10
Location ID: 328052



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: DUNCAN D #20-10
Location ID: 328052



Photo 5. Photo taken of ground cover at the location. Photo illustrates bare ground, straw mulch, and weedy annual vegetation.



Photo 6. Photo taken of the access road to the location, facing southeast. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed across the access road.



Inspection Photos
Location Name: DUNCAN D #20-10
Location ID: 328052



Photo 7. Photo taken of the tank battery location, facing northeast. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation was observed across the location.



Photo 8. Photo taken of the tank battery location, facing east. See comments under Photo 7.



Inspection Photos
Location Name: DUNCAN D #20-10
Location ID: 328052



Photo 9. Photo taken of the tank battery location, facing southwest. See comments under Photo 7.



Photo 10. Photo taken of the reference area for the location, south of the location, facing west. Photo illustrates sand sagebrush (*Artemisia filifolia*), perennial grass, and annual vegetation.

