

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328176

Inspection Document #: 718800603

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNCAN D #20-16
Location ID: 328176



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-16
Location ID: 328176



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-16
Location ID: 328176



Photo 5. Photo taken of ground cover at the location. Photo illustrates drill rows from seeding, straw mulch, and weedy annual vegetation including Kochia (*Bassia scoparia*).



Photo 6. Photo taken of the access road to the location, facing northwest. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards as the access road is dominated by weedy annual vegetation.

Inspection Photos
Location Name: DUNCAN D #20-16
Location ID: 328176



Photo 11. Photo taken of the reference area for the location, north of the location, facing east. Photo illustrates sand sagebrush (*Artemisia filifolia*) and prairie sunflower (*Helianthus petiolaris*).

