

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 465088

Inspection Document #: 718800605

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNCAN D-63N64W/20SESE
Location ID: 465088



Photo 1. Photo taken of the tank battery location, facing northwest. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the tank battery location, facing south. See comments under Photo 1.

Inspection Photos

Location Name: DUNCAN D-63N64W/20SESE

Location ID: 465088



Photo 3. Photo taken from the tank battery location, facing southeast. See comments under Photo 1.



Photo 4. Photo taken of the access road to the location, facing northwest. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards as the access road is dominated by weedy annual vegetation.



Inspection Photos
Location Name: DUNCAN D-63N64W/20SESE
Location ID: 465088



Photo 5. Photo taken of the reference area for the location, north of the location, facing east. Photo illustrates sand sagebrush (*Artemisia filifolia*) and prairie sunflower (*Helianthus petiolaris*).

