

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 305945

Inspection Document #: 718800609

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LIAM D #34-11
Location ID: 305945



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including cheatgrass (*Bromus tectorum*) was observed across the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: LIAM D #34-11
Location ID: 305945



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: LIAM D #34-11
Location ID: 305945



Photo 5. Photo taken of ground cover at the location. Photo illustrates cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the reference area for the location, south of the location, facing south. Photo illustrates perennial grass vegetation and weedy annual vegetation including cheatgrass (*Bromus tectorum*).