

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 305946

Inspection Document #: 718800614

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LIAM D #34-12
Location ID: 305946



Photo 1. Photo taken from the well location, facing North. Photo illustrates that vegetation establishment does not meet Rule 1004 standards. Gravel and weedy annual vegetation, including cheatgrass (*Bromus tectorum*), were observed across the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: LIAM D #34-12
Location ID: 305946



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: LIAM D #34-12
Location ID: 305946



Photo 5. Photo taken of ground cover at the location. Photo illustrates gravel and weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the access road to the location, facing southeast. Photo illustrates that final reclamation at the location does not meet Rule 1004 standards as gravel and weedy annual vegetation were observed across the location.

Inspection Photos
Location Name: LIAM D #34-12
Location ID: 305946



Photo 7. Photo taken of the access road to the location, facing northwest. Photo illustrates midstream equipment remains along the access road.



Photo 8. Photo taken of the reference area to the location, southeast of the location, facing southeast. Photo illustrates sand sagebrush (*Artemisia filifolia*), perennial grass, and cheatgrass (*Bromus tectorum*).

