

# Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 424203

Inspection Document #: 718800616

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Liam #D34-33  
Location ID: 424203



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Bare ground and weedy annual vegetation, including cheatgrass (*Bromus tectorum*), were observed across the location.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: Liam #D34-33  
Location ID: 424203



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: Liam #D34-33  
Location ID: 424203



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates bare ground and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 6.** Photo taken of the access road to the well location, facing southeast. Photo illustrates final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards and cheatgrass (*Bromus tectorum*) was observed across the location.

Inspection Photos  
Location Name: Liam #D34-33  
Location ID: 424203



**Photo 7.** Photo taken of the tank battery location, facing southeast. Photo illustrates that final reclamation at the location does not meet Rule 1004 standards as gravel and weedy annual vegetation were observed across the location.



**Photo 8.** Photo taken of the tank battery location, facing east. See comments under Photo 7.

Inspection Photos  
Location Name: Liam #D34-33  
Location ID: 424203



**Photo 9.** Photo taken of the tank battery location, facing south. See comments under Photo 7.



**Photo 10.** Photo taken of the tank battery location, facing west. See comments under Photo 7.

Inspection Photos  
Location Name: Liam #D34-33  
Location ID: 424203



**Photo 11.** Photo taken of ground cover at the tank battery location. Photo illustrates gravel and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 12.** Photo taken of the reference area for the location, west of the location, facing south. Photo illustrates perennial grass vegetation, sand sagebrush (*Artemisia filifolia*), and cheatgrass (*Bromus tectorum*).