

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0584 Entrance to location



Photo # 0585 Location

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0586 Location



Photo # 0589 Location

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0630 SW corner of location



Photo # 0631 NW corner of location

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0632 NE corner of location



Photo # 0633 SE corner of location

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0592 Wildlife hazard



Photo # 0593 Wildlife hazard

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0594 Wildlife hazard



Photo # 0595 Wildlife hazard

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0600 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 0609 Battery sign lacks quarter/quarter section information/not in compliance with CECMC rule

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0612 Open ended piping on tank/wildlife hazard/available for entry by wildlife

Photo # 0613 Open ended piping on tank/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0614 Open ended piping on tank/wildlife hazard/available for entry by wildlife



Photo # 0618 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0620 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 0621 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 13 PAD

Location ID: 315196

Date: 07/22/2025



Photo # 0622 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

