

KPK  
McCallum 100  
Location ID: 324660



Location



Location

KPK  
 McCallum 100  
 Location ID: 324660

7/29/25, 10:16 AM  
 +40.773905, -106.237558 ±3.53r  
 353° I  
 ECM

Form 21  
 (Rev. 8/15)

Click here to reset the form  
 State of Colorado  
 Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

OGCC Operator Number: 48290  
 Name of Operator: KLF RAUFMAN COMPANY INC. Victoria Lutzmann  
 Address: 1700 LINCOLN STREET SUITE 4550 Ph: 303-829-4822  
 City: DENVER State: CO Zip: 80202 Email: klf@raufman.com  
 API Number: 05-057-06187 Well ID: McCallum 100-100  
 Well Field Name: McCallum Unit Well Path Name: 100  
 Location Code: S20W Section: 29N Range: 29W Meridian: 10R  
 Last Well Date: 7/29/25

SHUT-IN PRODUCTION WELL  INJECTION WELL

Test Type:  
 Test to Maintain W/OA Status  Well J-C  Relief Valve  
 Verification of Repairs  Annul. of MC Test

Describe Repairs or Other Well Activities:

Wellbore Data at Time of Test

Production/Producing Interval	Perforated Interval	Surf Interval	Casing Top
PRREB	1458-1474		

Tabling Casing/Annulus Test

Tabling Date	Tabling Depth	Top Casing Depth	Multiple Perforations
2.375	1423'	1423'	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Test Date: 7/29/25  
 Wellbore Depth: 1423'  
 Casing Pressure Start Test: Casing Pressure: 11.00 psi

Test Witnessed by State Representative?  
 Yes  No

OGCC Field Representative: Scott Ramsey

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rick Kano  
 Signed: Rick Kano Title: w/o supervisor Date: 7/29/25

OGCC Approval:  
 Conditions of Approval, if any:

Form 21