

Inspection Photos

Location Name: WELD COUNTY USX AB-67N64W/19SENE

Location #: 410070



Photo #1

Weld County USX AB 19-07PD (123-30265) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.



Photo #2

Weld County USX AB 19-07PD, 19-08P Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (2-Wells)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: WELD COUNTY USX AB-67N64W/19SENE

Location #: 410070



Photo #3

Weld County USX AB 19-07PD, 19-08P Wellsite(s)

Plugged & Abandoned | PA (2-Wells)

Wellsite(s) entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources