

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 1SWSE

Location # 324372

Facility # 456926



Photo # 5652 Domestic tap



Photo # 5653 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 1SWSE

Location # 324372

Facility # 456926




Photo # 5654 Domestic tap



Photo # 5655 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 1SWSE

Location # 324372

Facility # 456926



Photo # 5656 Domestic tap



Photo # 5657 PRV vent line on domestic tap does not comply with CECMC pressure safety device rules & general safety rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 1SWSE

Location # 324372

Facility # 456926



Photo # 5658 PRV vent line on domestic tap does not comply with CECMC pressure safety device rules & general safety rules

