

Inspection Photos

06/05/2025

Operator: FULCRUM ENERGY OPERATING- #10805

Location ID: 324750

Inspection Document #: 712300164

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Buffalo Ditch 2-32H Pad
Location ID: 324750



Photo 1. Photos 1-4 taken at the wellhead, illustrating Location overview facing north, east, south, and west.



Photo 2. See comments under Photo 1.

Inspection Photos
Location Name: Buffalo Ditch 2-32H Pad
Location ID: 324750



Photo 3. See comments under Photo 1.



Photo 4. See comments under Photo 1.

Inspection Photos
Location Name: Buffalo Ditch 2-32H Pad
Location ID: 324750



Photo 5. Photo taken of the access road from the entrance of the Location, facing east. The access road has not been recontoured, removed of gravel, alleviated of compaction or re-seeded. Reclaim the access road per 1004.a. and 1004.d.

Photo 6. Photo shows aerial imagery, taken from Google Earth 10/13/2024, showing the access road that remains un-reclaimed (Red rectangle).

Inspection Photos
Location Name: Buffalo Ditch 2-32H Pad
Location ID: 324750



Photo 7. Photo taken of the seeded area, primarily Triticale.



Photo 8. Photo taken from the northeastern portion, facing southwest. Photo illustrates some bare spots remain without vegetation.

Inspection Photos
Location Name: Buffalo Ditch 2-32H Pad
Location ID: 324750



Photo 9. Photos 9-10 illustrating examples of undesirable plants species (e.g., Canada Thistle and Russian Thistle).



Photo 10. See comments under Photo 9.



Inspection Photos
Location Name: Buffalo Ditch 2-32H Pad
Location ID: 324750



Photo 11. Photo illustrates that debris/ trash still remains on Location.



Photo 12. Photo taken of what appears to be a well-marker; example of observed trash (metal sheet).

Inspection Photos
Location Name: Buffalo Ditch 2-32H Pad
Location ID: 324750



Photo 13. Photos 13-14 taken of the reference area vegetation, primarily sagebrush.



Photo 14. See comments under Photo 13.

