

Inspection Photos
Location Name: Yenter, C 2-21
API Number: 125-07157



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Yenter, C 2-21
API Number: 125-07157



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Yenter, C 2-21
API Number: 125-07157



7. View of produced water tank at gathering location. Note damaged sign.



8. Gathering location overview.