

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP BIG HORSE DRAW 26-2 PAD

Location ID: 315231

Date: 07/23/2025



Photo # 0724 Entrance to location



Photo # 0729 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP BIG HORSE DRAW 26-2 PAD

Location ID: 315231

Date: 07/23/2025



Photo # 0735 Location



Photo # 0755 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP BIG HORSE DRAW 26-2 PAD

Location ID: 315231

Date: 07/23/2025



Photo # 0756 SW corner of location



Photo # 0757 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP BIG HORSE DRAW 26-2 PAD

Location ID: 315231

Date: 07/23/2025



Photo # 0758 NE corner of location



Photo # 0739 Pit Facility #103879 lat/long is incorrect in the CECMC database/not in compliance with CECMC rules