

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0769 Entrance to location



Photo # 0779 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0770 Location



Photo # 0774 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0777 Location



Photo # 0802 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0803 NW corner of location



Photo # 0804 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0805 SE corner of location



Photo # 0773 Wellhead sign lacks required information/not in compliance with CECMC rules

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0784 Hole in meter house open to wildlife/available for entry by wildlife



Photo # 0789 Stockpiled soils with no BMP's

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0792 Stockpiled soils with no BMP's



Photo # 0798 Stockpiled soils with no BMP's

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0800 Stockpiled soils with no BMP's



Photo # 0815 Debris

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 07/24/2025



Photo # 0816 Debris



Photo # 0817 Unmarked deadman