

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOSS NER 413-6 Pad

Location ID: 324377



Photo # 5479 From entrance to location




Photo # 5480 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOSS NER 413-6 Pad

Location ID: 324377



Photo # 5481 Location



Photo # 5482 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOSS NER 413-6 Pad

Location ID: 324377



Photo # 5483 Location



Photo # 5484 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOSS NER 413-6 Pad

Location ID: 324377




Photo # 5485 Location



Photo # 5486 Methanol tank has label with previous operators name on it

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOSS NER 413-6 Pad

Location ID: 324377



Photo # 5487 Production tank showing signs of corrosion



Photo # 5488 Production tank showing signs of corrosion

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOSS NER 413-6 Pad

Location ID: 324377



Photo # 5489 Barbed wire fence needs maintenance/wildlife hazard



Photo # 5490 Barbed wire fence needs maintenance/wildlife hazard

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOSS NER 413-6 Pad

Location ID: 324377



Photo # 5491 Barbed wire fence needs maintenance/wildlife hazard



Photo # 5492 Barbed wire fence needs maintenance/wildlife hazard