

# Inspection Photos

07/03/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 312590

**Inspection Doc:** 719200046

Mesa County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 312590



**Photo 1:** Photo taken provides an overview of the reclaimed access road on the northern portion of the Location. The road has been de-compacted, recontoured and reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 312590



**Photo 2:** Photo taken from the central portion of the Location and provides an overview looking south.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 312590



**Photo 3:** Photo taken from the central portion of the Location and provides an overview looking east.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 312590



**Photo 4:** Photo taken from the central portion of the Location and provides an overview looking west. Reclamation is progressing towards 1004 requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 312590



**Photo 5:** Photo taken from the southwest portion of the Location and shows an example of houndstongue dispersed throughout the area. Comply with Rule 1004.e. and remove undesirable plant species.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources