

# Final Reclamation and Stormwater Inspection

July 28, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location ID: 331652

Well Name: FEDERAL NOAA #11-32

Inspection Document #: 718600810

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FEDERAL NOAA #11-32  
Location ID: 331652



**Photo 1.** Picture taken at the entrance of the access road. The main access road appears to be preexisting to oil and gas.



**Photo 2.** Picture taken from the main access road looking west down the access road and across the location. It appears that reclamation was conducted on location with evidence of crimped straw. Desirable germination was not observed on the access road at the time of inspection. Vegetation on location is primarily undesirable weed kochia.



Inspection Photos  
Location Name: FEDERAL NOAA #11-32  
Location ID: 331652



**Photo 3.** Looking west across the wellbore area. No oil and gas equipment remains. Crimped straw is present in this area. Desirable vegetation germination was not observed at the time of inspection. A large bare soil patch is present around the wellbore. Vegetation on location is primarily undesirable weed kochia.



**Photo 4.** Looking north from the wellbore. See photo 3 comments.

Inspection Photos  
Location Name: FEDERAL NOAA #11-32  
Location ID: 331652



**Photo 5.** Looking west from the wellbore. See photo 3 comments.



**Photo 6.** Looking south from the wellbore. See photo 3 comments.



Inspection Photos  
Location Name: FEDERAL NOAA #11-32  
Location ID: 331652



**Photo 7.** Looking east from the wellbore. See photo 3 comments.



**Photo 8.** Reference vegetation to the north of the well location. Reference vegetation is primarily undesirable weeds such as kochia.

