

Inspection Photos
Location: Sekich P19-27D Tank Battery
Facility ID: 451588, Spill ID 489542



Photo 1 – Facing Excavation from County Road 32 facing South

Inspection Photos
Location: Sekich P19-27D Tank Battery
Facility ID: 451588, Spill ID 489542



Photo 2 – Facing Southeast viewing inadequate fencing of excavation



Inspection Photos
Location: Sekich P19-27D Tank Battery
Facility ID: 451588, Spill ID 489542




Photo 3 – Facing Southeast viewing excavation with sidewalls collapsing



Inspection Photos
Location: Sekich P19-27D Tank Battery
Facility ID: 451588, Spill ID 489542



Photo 4 – Facing Northeast viewing gray staining on sidewall and standing water

Inspection Photos
Location: Sekich P19-27D Tank Battery
Facility ID: 451588, Spill ID 489542



Photo 5 – Facing Northeast towards open excavation

