

Inspection Photos
Location: LEMON 12-23A/KUECHLE Facility TB
Facility ID: 487119




Photo 1 – Facing West towards open excavations

Inspection Photos
Location: LEMON 12-23A/KUECHLE Facility TB
Facility ID: 487119



Photo 2 – Facing West towards open excavations



Inspection Photos
Location: LEMON 12-23A/KUECHLE Facility TB
Facility ID: 487119



Photo 3 – Open excavation with abandoned pipe



Inspection Photos
Location: LEMON 12-23A/KUECHLE Facility TB
Facility ID: 487119



Photo 4 – Facing Southwest towards unlabeled stockpile with inadequate BMPs



Inspection Photos
Location: LEMON 12-23A/KUECHLE Facility TB
Facility ID: 487119



Photo 5 – Facing South towards second unlabeled stockpile with inadequate BMPs

Inspection Photos
Location: LEMON 12-23A/KUECHLE Facility TB
Facility ID: 487119



Photo 6— Facing East towards open excavation and third unlabeled stockpile with inadequate BMPs and fencing

