

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 06/18/2025 Document Number: 404245186

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Erik Mickelson Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-4306 Address: P O BOX 173779 Fax: () City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 323420 Initial Form 19 or 27 Document number: Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6 County: WELD Field Name: WATTENBERG Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 764985 Facility Name: Reigle 270197 Facility Type: Domestic Well Location: QtrQtr: NENW Sec: 4 Twp: 2N Range: 65W Meridian: 6 County Name: WELD Latitude: 40.173949 Longitude: -104.669679

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 127472 Document Name: Size of file in bytes: 22807 File Name: 2025_03_13_Reigle 270197 Trip Blank SGS ECMC.xlsx SampleType: Matrix: Facility ID: 764985 Sample ID: 668136 Sample Name: Reigle 270197 Sample Date: 03/13/2025 Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA71139-1

Batch ID: 127475	Document Name: Size of file in bytes: 20450	File Name: 2025_03_13_Reigle 270197 Isotech NG4 ECMC.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 764985	Sample ID: 668139	Sample Name: Reigle 270197
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH
		Lab Sample ID: 960390
Batch ID: 127474	Document Name: Size of file in bytes: 33340	File Name: 2025_03_13_Reigle 270197 SGS ECMC 1.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 764985	Sample ID: 668138	Sample Name: Reigle 270197
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest
		Lab Sample ID: DA71138-1
Batch ID: 127475	Document Name: Size of file in bytes: 20450	File Name: 2025_03_13_Reigle 270197 Isotech NG4 ECMC.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 764985	Sample ID: 668140	Sample Name: Reigle 270197
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH
		Lab Sample ID: 960390
Batch ID: 127473	Document Name: Size of file in bytes: 24242	File Name: 2025_03_13_Reigle 270197 SGS ECMC 2.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 764985	Sample ID: 668137	Sample Name: Reigle 270197
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest
		Lab Sample ID: DA71138-1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
764985	404245208	2025_03_13_Reigle_270197 _PrePost.jpg	Photographs	JPG
764985	404245211	2025_03_13_Reigle_270197 _Wellhead.jpg	Photographs	JPG
764985	404245193	2025_03_13_Reigle 270197 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
764985	404245212	2025_03_13_Reigle_270197 _Wellhead_Loc.jpg	Photographs	JPG
764985	404245202	2025_03_13_Reigle 270197 Isotech NG4 Locked.pdf	Analytical Laboratory Report	PDF
764985	404245210	2025_03_13_Reigle_270197 _Spigot_Loc.jpg	Photographs	JPG
764985	404245205	2025_03_13_Reigle 270197 SGS.pdf	Analytical Laboratory Report	PDF
764985	404245207	2025_03_13_Reigle_27019 7_FS_ECMC.pdf	Field Data Report	PDF
764985	404245209	2025_03_13_Reigle_270197 _Spigot.jpg	Photographs	JPG

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	08/01/2025
Total: 1 comment(s)		