

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 5689 From entrance to location



Photo # 5690 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 5691 Location




Photo # 5692 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 5693 Location




Photo # 5694 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 5695 Tank capacity incorrect




Photo # 5696 Tank capacity

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



**Photo # 5697 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5698 Barbed wire fence needs maintenance/wildlife hazard**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



**Photo # 5699 Barbed wire fence needs maintenance/wildlife hazard**